

Tree Removals Winter 2018/19

| Label | Address | Street          | On Street           | Species                              | Diameter | Maintenance       | Area          | Parks               | SiteID | Reason for Removal  |
|-------|---------|-----------------|---------------------|--------------------------------------|----------|-------------------|---------------|---------------------|--------|---|
| 1     | 135     | Beechwood Ave   | Beechwood Ave       | <i>Prunus cerasifera</i>             | 53       | Assessed Removal  | Gonzales      | N/A                 | 20033  | Advanced basal decay and shell wall minimum not met.                  |
| 2     | 1610    | Belcher Ave     | Belcher Ave         | <i>bv</i>                            | 54       | Assessed Removal  | South Jubilee | N/A                 | 18497  | Decay within the scaffold union, a lean and crown dieback.            |
| 3     | 1145    | Burdett Ave     | Burdett Ave         | <i>Prunus cerasifera</i>             | 55       | Assessed Removal  | Fairfield     | N/A                 | 16062  | Decay in the base and trunk, lack of inner canopy.                    |
| 4     | 103     | Cambridge St    | Cambridge St        | <i>Prunus yedoensis</i>              | 52       | Assessed Removal  | Fairfield     | N/A                 | 17868  | Extensive decay in the trunk.   |
| 5     | 156     | Cambridge St    | Cambridge St        | <i>Prunus yedoensis</i>              | 55       | Assessed Removal  | Fairfield     | N/A                 | 17927  | Inadequate shell wall with a lean.                                    |
| 6     | 865     | Catherine St    | Catherine St        | <i>Prunus accolade</i>               | 23       | Assessed Removal  | Victoria      | N/A                 | 29980  | Dead  |
| 7     | 3100    | Cecelia Ravine  | Cecelia Ravine Park | <i>Thuja plicata</i>                 | 20       | Assessed Removal  | Burnside      | Cecelia Ravine Park | 26556  | Dead  |
| 8     | 3100    | Cecelia Ravine  | Cecelia Ravine Park | <i>Acer macrophyllum</i>             | 40       | Assessed Removal  | Burnside      | Cecelia Ravine Park | 26503  | Severe decay from the trunk from the base to the scaffolds.           |
| 9     | 3100    | Cecelia Ravine  | Cecelia Ravine Park | <i>Acer macrophyllum</i>             | 45       | Assessed Removal  | Burnside      | Cecelia Ravine Park | 26502  | Severe decay from the trunk from the base to the scaffolds.           |
| 10    | 3100    | Cecelia Ravine  | Cecelia Ravine Park | <i>Thuja plicata</i>                 | 18       | Assessed Removal  | Burnside      | Cecelia Ravine Park | 26559  | Dead  |
| 11    | 508     | Cecelia Rd      | Cecelia Rd          | <i>Prunus cerasifera</i>             | 45       | Assessed Removal  | Burnside      | N/A                 | 27709  | Crown dieback, extensive basal decay with Ganoderma.                  |
| 12    | 1       | Cook St         | Cook St             | <i>Aesculus hippocastanum</i>        | 94       | Assessed Removal  | Fairfield     | N/A                 | 4040   | Severe decay in the scaffold union, with included bark.               |
| 13    | 25      | Cook St         | Cook St             | <i>Aesculus carnea</i>               | 14       | Assessed Removal  | Fairfield     | N/A                 | 4044   | Dead  |
| 14    | 271     | Cook St         | Oxford St           | <i>Prunus avium</i>                  | 51       | Assessed Removal  | Fairfield     | N/A                 | 16561  | Inadequate well wall thickness with Ganoderma.                        |
| 15    | 770     | Cormorant St    | Blanshard St        | <i>Carpinus betulus 'Fastigiata'</i> | 30       | Assessed Removal  | Downtown      | N/A                 | 9958   | Severe canopy decline.  |
| 16    | 521     | Craigflower Rd  | Craigflower Rd      | <i>Acer macrophyllum</i>             | 64       | Assessed Removal  | Victoria      | Banfield Park       | 12990  | Extensive internal decay within the base of trunk.                    |
| 17    | 100     | Dallas Rd       | Dallas Rd           | <i>Prunus cerasifera</i>             | 43       | Assessed Removal  | Fairfield     | Beacon Hill Park    | 1603   | Decay at the base of the tree with crown decline.                     |
| 18    | 100     | Dallas Rd       | Dallas Rd           | <i>Cedrus atlantica</i>              | 66       | Assessed Removal  | James Bay     | Beacon Hill Park    | 8847   | Significant canopy decline.   |
| 19    | 100     | Dallas Rd       | Dallas Rd           | <i>Cedrus atlantica</i>              | 55       | Assessed Removal  | James Bay     | Beacon Hill Park    | 8844   | Significant canopy decline.   |
| 20    | 100     | Dallas Rd       | Dallas Rd           | <i>Abies pinsapo</i>                 | 47       | Assessed Removal  | Fairfield     | Beacon Hill Park    | 8275   | Severe canopy decline with no internal growth.                        |
| 21    | 100     | Dallas Rd       | Dallas Rd           | <i>Pinus sylvestris</i>              | 64       | Assessed Removal  | Fairfield     | Beacon Hill Park    | 4443   | Dead  |
| 22    | 100     | Dallas Rd       | Dallas Rd           | <i>Abies grandis</i>                 | 53       | Assessed Removal  | Fairfield     | Beacon Hill Park    | 4632   | Severe canopy decline with a loss in vigor.                           |
| 23    | 100     | Dallas Rd       | Dallas Rd           | <i>Abies grandis</i>                 | 25       | Assessed Removal  | Fairfield     | Beacon Hill Park    | 4649   | Severe canopy decline with a loss in vigor.                           |
| 24    | 100     | Dallas Rd       | Dallas Rd           | <i>Aesculus hippocastanum</i>        | 85       | Assessed Removal  | Fairfield     | Beacon Hill Park    | 8681   | Severe inclusion and limited soundwood down to root collar.           |
| 25    | 100     | Dallas Rd       | Dallas Rd           | <i>Pinus sylvestris</i>              | 31       | Assessed Removal  | James Bay     | Beacon Hill Park    | 1786   | Dead  |
| 26    | 100     | Dallas Rd       | Dallas Rd           | <i>Pinus sylvestris</i>              | 32       | Assessed Removal  | James Bay     | Beacon Hill Park    | 1777   | Dead  |
| 27    | 100     | Dallas Rd       | Dallas Rd           | <i>Pinus ponderosa</i>               | 30       | Assessed Removal  | James Bay     | Beacon Hill Park    | 1406   | Dead  |
| 28    | 100     | Dallas Rd       | Dallas Rd           | <i>Pinus sylvestris</i>              | 40       | Assessed Removal  | James Bay     | Beacon Hill Park    | 1329   | Dead  |
| 29    | 100     | Dallas Rd       | Dallas Rd           | <i>Cedrus atlantica</i>              | 32       | Assessed Removal  | James Bay     | Beacon Hill Park    | 1122   | Dead  |
| 30    | 100     | Dallas Rd       | Dallas Rd           | <i>Pinus monticola</i>               | 49       | Assessed Removal  | James Bay     | Beacon Hill Park    | 2308   | Dead  |
| 31    | 100     | Dallas Rd       | Dallas Rd           | <i>Quercus garryana</i>              | 43       | Assessed Removal  | James Bay     | Beacon Hill Park    | 2972   | Dead  |
| 32    | 2898    | Douglas St      | Dunedin St          | <i>Prunus cerasifera</i>             | 55       | Assessed Removal  | Burnside      | N/A                 | 27613  | Extensive decay at the base with heart rot in the scaffold.           |
| 33    | 2175    | Dowler Pl       | Princess Ave        | <i>Prunus cerasifera</i>             | 61       | Assessed Removal  | North Park    | N/A                 | 19000  | Extensive decay at the base and a cavity with decay in the scaffolds. |
| 34    | 534     | Dunedin St      | Dunedin St          | <i>Prunus cerasifera</i>             | 57       | Assessed Removal  | Burnside      | N/A                 | 27669  | Basal decay, wounding, and included bark.                             |
| 35    | 653     | Dunedin St      | Dunedin St          | <i>Prunus cerasifera</i>             | 40       | Assessed Removal  | Burnside      | N/A                 | 27614  | Extensive decay in the base, heart rot in the scaffolds.              |
| 36    | 414     | Durban St       | Durban St           | <i>Aesculus carnea</i>               | 70       | Assessed Removal  | Fairfield     | N/A                 | 16479  | Crack in scaffold union.  |
| 37    | 439     | Durban St       | Durban St           | <i>Prunus cerasifera</i>             | 53       | Assessed Removal  | Fairfield     | N/A                 | 16465  | Advanced decay at scaffold attachment with poor wound response.       |
| 38    | 748     | Esquimalt Rd    | Rothwell St         | <i>Prunus cerasifera</i>             | 49       | Assessed Removal  | Victoria      | Z Add 01            | 34370  | Advanced basal decay.   |
| 39    | 1113    | Fairfield Rd    | Fairfield Rd        | <i>Prunus serrulata</i>              | 50       | Assessed Removal  | Fairfield     | N/A                 | 16939  | Sparse crown with extensive dieback.                                  |
| 40    | 1495    | Fairfield Rd    | Fairfield Rd        | <i>Prunus serrulata kwanzan</i>      | 46       | Assessed Immediat | Fairfield     | Ross Bay Cemetery   | 7876   | Extensive canopy decline, and a loss in vigor.                        |
| 41    | 1495    | Fairfield Rd    | Fairfield Rd        | <i>Ulmus pumila</i>                  | 59       | Assessed Immediat | Fairfield     | Ross Bay Cemetery   | 7977   | Significant decay in the base with the area prone to windthrow.       |
| 42    | 1495    | Fairfield Rd    | Fairfield Rd        | <i>Prunus cerasifera</i>             | 45       | Assessed Immediat | Fairfield     | Ross Bay Cemetery   | 7981   | Decay at the base and trunk, and a cavity with brown rot.             |
| 43    | 1495    | Fairfield Rd    | Fairfield Rd        | <i>Prunus cerasifera</i>             | 44       | Assessed Removal  | Fairfield     | Ross Bay Cemetery   | 7992   | Decay at the base with significant canopy decline.                    |
| 44    | 1495    | Fairfield Rd    | Fairfield Rd        | <i>Salix x sepulcralis Simonkai</i>  | 76       | Assessed Immediat | Fairfield     | Ross Bay Cemetery   | 13349  | Canopy decline and internal decay.                                    |
| 45    | 1495    | Fairfield Rd    | Fairfield Rd        | <i>Prunus cerasifera</i>             | 53       | Assessed Removal  | Fairfield     | Ross Bay Cemetery   | 13156  | Decay in the base of the tree, the trunk and scaffolds.               |
| 46    | 1495    | Fairfield Rd    | Fairfield Rd        | <i>Prunus cerasifera</i>             | 40       | Assessed Removal  | Fairfield     | Ross Bay Cemetery   | 7406   | Extensive decay at the base of the tree with crown decline.           |
| 47    | 1495    | Fairfield Rd    | Fairfield Rd        | <i>Prunus cerasifera</i>             | 94       | Assessed Removal  | Fairfield     | Ross Bay Cemetery   | 13571  | Inadequate shell wall thickness with a severe lean.                   |
| 48    | 1663    | Fairfield Rd    | Fairfield Rd        | <i>Prunus cerasifera</i>             | 61       | Assessed Removal  | Gonzales      | N/A                 | 20169  | Extensive crown decline and a loss in vigor.                          |
| 49    | 2900    | Galloping Goose | Galloping Goose     | <i>Populus nigra</i>                 | 39       | Assessed Removal  | Burnside      | Galloping Goose     | 31631  | Dead  |
| 50    | 64      | Gorge Rd E      | Gorge Rd E          | <i>Prunus cerasifera</i>             | 42       | Assessed Removal  | Burnside      | N/A                 | 28280  | Basal decay with canopy decline and poor vitality.                    |
| 51    | 1101    | Government St   | Government St       | <i>Prunus sargentii</i>              | 12       | Assessed Removal  | Downtown      | N/A                 | 9611   | Dead  |
| 52    | 47      | Howe St         | Howe St             | <i>Prunus cerasifera</i>             | 43       | Assessed Removal  | Fairfield     | N/A                 | 17707  | Inadequate shell wall thickness with crown dieback.                   |
| 53    | 136     | Howe St         | Howe St             | <i>Sorbus intermedia</i>             | 12       | Assessed Immediat | Fairfield     | N/A                 | 17798  | Extensive decay and wound in trunk.                                   |
| 54    | 160     | Howe St         | Howe St             | <i>Prunus cerasifera</i>             | 55       | Assessed Removal  | Fairfield     | N/A                 | 17805  | Extensive decay at the base with crown dieback.                       |

Tree Removals Winter 2018/19

| Label | Address | Street        | On Street     | Species                              | Diameter | Maintenance       | Area            | Parks         | SiteID | Reason for Removal   |
|-------|---------|---------------|---------------|--------------------------------------|----------|-------------------|-----------------|---------------|--------|--|
| 55    | 261     | Howe St       | Howe St       | <i>Prunus cerasifera</i>             | 56       | Assessed Removal  | Fairfield       | N/A           | 17246  | Extensive decay at the base and brown rot in the scaffolds.      |
| 56    | 3165    | Irma St       | Irma St       | <i>Acer rubrum 'Armstrong'</i>       | 41       | Assessed Removal  | Burnside        | N/A           | 28365  | Extensive canopy decline.  |
| 57    | 1015    | Joan Cres     | Joan Cres     | <i>Amelanchier grandiflora</i>       | 5        | Assessed Removal  | Rockland        | N/A           | 20922  | Dead   |
| 58    | 1737    | Kings Rd      | Kings Rd      | <i>Betula pendula</i>                | 36       | Assessed Removal  | North Jubilee   | N/A           | 25591  | A loss in vigor and significant deadwood.                        |
| 59    | 243     | Kingston St   | Kingston St   | <i>Prunus cerasifera</i>             | 40       | Assessed Removal  | James Bay       | N/A           | 14868  | Extensive decay in the base and throughout the trunk.            |
| 60    | 325     | Linden Ave    | Mckenzie St   | <i>Prunus cerasifera</i>             | 64       | Assessed Removal  | Fairfield       | N/A           | 17889  | Extensive decay at the base with crown dieback.                  |
| 61    | 1       | Lotus St      | Lotus St      | <i>Prunus species</i>                | 33       | Assessed Removal  | Burnside        | N/A           | 27382  | Extensive canopy decline.  |
| 62    | 59      | Lotus St      | Lotus St      | <i>Cedrus atlantica</i>              | 104      | Assessed Removal  | Burnside        | N/A           | 34983  | Dead   |
| 63    | 623     | Manchester Rd | Manchester Rd | <i>Prunus cerasifera</i>             | 47       | Assessed Removal  | Burnside        | N/A           | 27629  | Extensive basal decay.   |
| 64    | 1000    | Mcclure St    | Vancouver St  | <i>Acer pseudoplatanus</i>           | 49       | Assessed Removal  | Fairfield       | N/A           | 15416  | Dead   |
| 65    | 128     | Montreal St   | Ladysmith St  | <i>Aesculus carnea</i>               | 40       | Assessed Removal  | James Bay       | N/A           | 14662  | Dead tree with girdling root.                                    |
| 66    | 721     | Moss St       | Moss St       | <i>Prunus cerasifera</i>             | 39       | Assessed Removal  | Rockland        | N/A           | 21300  | Basal decay, wounding in the trunk and canopy decline.           |
| 67    | 1427    | Myrtle Ave    | Myrtle Ave    | <i>Betula pendula</i>                | 28       | Assessed Removal  | Oaklands        | N/A           | 23034  | Extensive canopy decline.  |
| 68    | 275     | Niagara St    | Niagara St    | <i>Prunus avium</i>                  | 46       | Assessed Removal  | James Bay       | N/A           | 13692  | Poor vitality.   |
| 69    | 147     | Ontario St    | Montreal St   | <i>Prunus cerasifera</i>             | 44       | Assessed Removal  | James Bay       | N/A           | 14012  | Advanced decay at the base and shell wall minimums not met.      |
| 70    | 1005    | Pakington St  | Vancouver St  | <i>Prunus species</i>                | 47       | Assessed Removal  | Fairfield       | N/A           | 15721  | Dead   |
| 71    | 909     | Pembroke St   | Pembroke St   | <i>Acer platanoides</i>              | 64       | Assessed Removal  | North Park      | N/A           | 18704  | Extensive decay in the trunk with poor vitality.                 |
| 72    | 1030    | Princess Ave  | Princess Ave  | <i>Prunus cerasifera</i>             | 56       | Assessed Removal  | North Park      | N/A           | 18748  | Advanced decay in the base with a large wound in the scaffold.   |
| 73    | 2275    | Quadra St     | Quadra St     | <i>Chamaecyparis lawsoniana</i>      | 44       | Assessed Removal  | North Park      | Central Park  | 6284   | Dead   |
| 74    | 2275    | Quadra St     | Quadra St     | <i>Chamaecyparis lawsoniana</i>      | 28       | Assessed Removal  | North Park      | Central Park  | 6290   | Dead   |
| 75    | 924     | Queens Ave    | Queens Ave    | <i>Crataegus oxyacantha</i>          | 8        | Assessed Removal  | North Park      | N/A           | 18781  | Significant canopy decline.                                      |
| 76    | 954     | Queens Ave    | Vancouver St  | <i>Prunus cerasifera</i>             | 45       | Assessed Removal  | North Park      | N/A           | 18766  | Extensive decay at the base with crown dieback.                  |
| 77    | 1010    | Queens Ave    | Vancouver St  | <i>Prunus cerasifera</i>             | 45       | Assessed Removal  | North Park      | N/A           | 18791  | Basal decay with canopy decline and a crack within the scaffold. |
| 78    | 600     | Richmond Ave  | Richmond Ave  | <i>Prunus cerasifera</i>             | 38       | Assessed Removal  | Rockland        | N/A           | 21135  | Basal decay with an extensive lean.                              |
| 79    | 1067    | Richmond Ave  | Richmond Ave  | <i>Betula pendula</i>                | 28       | Assessed Removal  | Gonzales        | N/A           | 20636  | Severe canopy decline with saprophytic fruiting bodies.          |
| 80    | 1550    | Richmond Ave  | Richmond Ave  | <i>Betula papyrifera</i>             | 58       | Assessed Immediat | South Jubilee   | N/A           | 18300  | Basal decay and thinning of the crown within a high target area. |
| 81    | 1342    | Rockland Ave  | Royal Terr    | <i>Chamaecyparis nootkatensis</i>    | 17       | Assessed Removal  | Rockland        | N/A           | 20846  | Dead   |
| 82    | 517     | Selkirk Ave   | Selkirk Ave   | <i>Betula pendula</i>                | 33       | Assessed Removal  | Victoria        | N/A           | 29302  | Bronze Birch Borer with extensive canopy decline.                |
| 83    | 570     | Selkirk Ave   | Selkirk Ave   | <i>Betula papyrifera</i>             | 40       | Assessed Removal  | Victoria        | Burleith Park | 30929  | Bronze Birch Borer with extensive canopy decline.                |
| 84    | 1912    | Shotbolt Rd   | Shotbolt Rd   | <i>Sorbus americana</i>              | 25       | Assessed Removal  | Gonzales        | N/A           | 19661  | Dead   |
| 85    | 3195    | Stevenson Pl  | Stevenson Pl  | <i>Crataegus x lavalleyi</i>         | 56       | Assessed Removal  | Hillside/Quadra | N/A           | 12091  | Extensive canopy decline and a loss in vigor.                    |
| 86    | 213     | Vancouver St  | Vancouver St  | <i>Prunus serrulata kwanzan</i>      | 65       | Assessed Removal  | Fairfield       | N/A           | 15631  | Loss of vigor and a low live crown ratio with Ganoderma.         |
| 87    | 219     | Vancouver St  | Vancouver St  | <i>Prunus subhirtella</i>            | 31       | Assessed Removal  | Fairfield       | N/A           | 15629  | Dead   |
| 88    | 490     | Vancouver St  | Vancouver St  | <i>Prunus species</i>                | 52       | Assessed Removal  | Fairfield       | N/A           | 15546  | Poor vitality with multiple cavities and poor structure.         |
| 89    | 743     | Vancouver St  | Vancouver St  | <i>Acer pseudoplatanus</i>           | 47       | Assessed Removal  | Fairfield       | N/A           | 15477  | Extensive decay throughout the base and trunk.                   |
| 90    | 2201    | Vancouver St  | Vancouver St  | <i>Robinia pseudoacacia</i>          | 71       | Assessed Removal  | North Park      | N/A           | 18743  | Extensive internal decay in the trunk.                           |
| 91    | 190     | Wilson St     | Bay St        | <i>Carpinus betulus 'Fastigiata'</i> | 4        | Assessed Removal  | Victoria        | Alston Green  | 29574  | Dead   |
| 92    | 350     | Windermere Pl | Windermere Pl | <i>Prunus cerasifera</i>             | 44       | Assessed Removal  | Fairfield       | N/A           | 15130  | Extensive basal decay with poor vitality.                        |